



Transmission: 4L60-E

Subject: Code 72 diagnostics (1993-95 applications with a PCM)

Application: GM

Issue Date: 1995

4L60-E

Code 72 Diagnostics (1993-95 Applications with a PCM)

One of the most common and difficult to diagnose 4L60-E concerns is code 72, vehicle speed sensor loss. It has shown itself to be a very common concern for both the dealer and independent shop. This bulletin is designed to address the code, and proper diagnostic steps required to locate the root cause of the problem. This bulletin will be followed with another showing component locations, as well as the most common causes for the code on each vehicle application.

Some service manuals may not adequately diagnose a code 72 condition, therefore a comeback is likely. Use of the following diagnostic strategies to assist with code 72 diagnosis of the 4L60-E transmission.


Circuit Operation

The 4L60-E transmission uses a vehicle speed sensor mounted to the transmission (or transfer case on 4X4 units). Mounted to the output shaft is a 40 toothed wheel. As the output shaft rotates, an AC signal is created. This signal is sent to a VSS buffer on all nonpassenger-car applications. (Passenger-car applications do not use and external buffer, therefore the AC signal is fed directly to the PCB.) The buffer (also known as a DRAC or DRAB) performs the following function:

- It converts the AC signal from the sensor to a digital DC signal for the various computers on the vehicle.
- It provides different frequency rates for the various vehicle computers.
- It allows for adjustment if the tire size or axle ratio is changed.

To perform these functions, the buffer is given a five volt signal from the vehicle's PCB on two circuits, 437 and 1697. Circuit 437 is used by the transmission shift points. Circuit 1697 is used by the PCB to determine road speed for uses such as vehicle overspeed fuel cutoff and idle air control valve position (Figure 1).

Illustrations courtesy of General Motors



Technical Bulletin #302

To signal the PCB, the buffer simply grounds and ungrounds the two circuits, based on the frequency of the signal received from the sensor. As the five volt signal is grounded, the signal voltage at the PCB is pulled down, close to zero volts. As the buffer ungrounds the circuit, the signal voltage will return to five volts. The PCB monitors the frequency of these signals to determine the vehicles actual road speed. By using a scan tool you will notice two readings in relation to vehicle speed, transmission output RPM and vehicle MPH. MPH readings represent circuit 1697 while output RPM readings refer to circuit 437.

Code 72 will set if the following conditions exist.

- The vehicle is in any range other than park or neutral:
- Engine RPM is greater than 200.
- Pressure switch assembly code 28 is not set.
- Output RPM indicates as RPM change of over 1000 RPM in less than 2 seconds.

OR

- The vehicle is in park or neutral.
- Engine RPM is greater than 200.
- Pressure switch assembly, code 28 is not set.
- Output RPM indicates a RPM change of over 2050 RPM in less than 2 seconds.

If code 72 is set the PCB will respond by:

- Defaulting to second gear. Once the default has occurred the vehicle will not shift, and the unit will start and stay in second gear.
- High line pressure.

Recovery

Next ignition cycle.

**(For Truck, Van and Sport Utility
Applications Using a PCM)**





Chart 'A' Code 72 or 72 and 24

NOTE: Code 72 may be set in conjunction with ABS codes, and the ABS lamp may be on.


Note: These charts are designed to diagnose gas applications, see schematic at the end of this bulletin for diesel pin applications.




NOTE: See chart 'C' for tips to common problems.

Chart 'B'

Scanner Indicates 0 MPH and 0 Output RPM



Gas Engine




Diesel to Gas 'Pin' Conversion Chart

The following is a conversion chart for using chart "A" and "B" with a diesel application. If there is not reference made for a pin in question, it is the same as the gas version.

Gas		to	Diesel	
Circuit #	Pin #	is	Circuit #	Pin #
400	C-1		818	C-4
150	C-8		450	C-8
350	C-9		250	C-9
437	F-12		437	C-15
1716/1697	C-11		834	C-14
1716/1697	F-13		834	D-8
824	C-14		824	C-15
822	J		822	M
821	G		821	L
Connectors				
C-267			C-229	
C-204			C-215	
C-240			C-200	
C-394			C-365	

Diesel Engines



Code Diagnosis Chart ‘C’

Concerns common to all applications:

- Excess grease packed into a connector. An excessive amount of grease in a terminal connector can cause poor electrical contact.
- The toothed-wheel for the VSS is loose on the output shaft.
- Extension housing or output shaft bushing is loose.
- Someone has added a ground for an add-on accessory, such as an alarm or two-way radio, to the PCM or DRAC (VSS buffer) ground circuits.
- An add-on accessory, such as an alarm or radio, is located too close to the DRAC which can cause electromagnetic interference problems. This condition may be indicated by noting a speedometer reading with the vehicle sitting still while the add-on device is powered up.
- Vehicle speed sensor, DRAC or PCM is faulty.
- Loss of terminal pin tension for the female terminals in any connector. All terminals are designed to withstand only a few connects and disconnects. Connecting and disconnecting the system's connectors will reduce the life expectancy of those terminals. This can allow an intermittent connection to occur. Loss of pin tension *will* cause damage to most terminals. To check for proper pin tension use the appropriate terminal tension gauge or use a spare male terminal of the correct size. To check the PCM and DRAC terminals use a .03+” drill or carburetor gauge. Both the PCM and DRAC use micro-pack terminals (round). Simply feel for a moderate drag when the male pin is inserted and removed. *Be sure to use the correct size and style of male terminal when testing for proper tension.*

Common concerns specific to model

- Safari and Astro Vans.....pg. 10
- S-10/T-10 Truck, Blazer and Jimmy.....pg. 12
- C/K Full Size Pickup, Yukon, Tahoe,
Suburban and Blazer.....pg. 14
- G Series, Full-Size Van.....pg. 15

Technical Bulletin #302

Common concerns specific to model: Safari and Astro Van

- Short to ground in VSS sensor circuit 821 or 822, on all steel drive versions. The problem is usually at the transfer case where the wiring harness is routed over the top. The harness generally rubs through on one of the flanges of the transfer case (figure 1).
- Short to ground in circuit 821 or 822 at the wiring clamp, behind the exhaust shield.
- Circuits 821 or 822 shorted at the engine cover bracket or valve cover.
- Water intrusion into the PCM connector C-240, causing terminal corrosion. Connector C-240 is mounted under the passenger side of the dash, next to the PCM (figure 2). Water intrusion into this area is usually due to a windshield leak in the right corner of the dash.

Circuit 420 (TCC) of the main harness is shorted to ground on the right-hand side of the engine (the wire rubs through on the engine cover bracket). This condition will also result in the transmission going to default mode, and will greatly affect other vehicle systems. Other systems affected will include: the shift interlock solenoid, speedometer and ABS... all of which will be inoperative since the problem will cause the brake fuse to fail, which is used to feed all of these brake systems.

- A loose or damaged toothed-wheel on the output shaft which is used for the VSS.
- Poor connection at terminal j or g in connector C-240.

If the connector is not fully latched, ABS code 37 may set in conjunction with code 72.




Figure 1







Figure 2

Illustrations courtesy of General Motors

- A loose or corroded battery ground bolt. This problem is generally ground G-102 (figure 3A) which is mounted under the water pump/power steering pump area of the block, or G-150 (figure 3B) which is mounted to the radiator core support. If these grounds are not corroded or loose, inspect ground G-197 (figure 3C) for a possible problem. A problem with G-150 may also cause the dash lamps to be dim.
- Extension housing or output shaft bushing loose.
- The vehicle speed sensor circuits are routed with the main vehicle harness. This harness travels along the bellhousing and enters the cab on the passenger side. If the harness is too close to any spark plug wires, a code 72 will result due to EMI. Reroute the plug wires away from the P-100 (pass through connector) area (figure 2, page 10).
- Loss of battery voltage to the bulkhead connector. (The bulkhead connector is located on the driver's side, close to the brake booster.)






Figure 4

S-10/T-10 Truck, Blazer and Jimmy

- Circuit 821 or 822 shorted to ground at the metal bracket below the distributor or as it crosses the top of the bellhousing (figure 4).
- Circuit 821 or 822 shorted to ground at the right hand valve cover area, heat stove or dipstick tube area.
- Short to ground in VSS circuit 821 (or 822, on four wheel drive versions). The problem is usually at the top of the transfer case where the wiring harness is routed over the top. The harness generally rubs through on one of the flanges of the transfer case, or becomes shorted to ground at one of the wiring harness hold-down clamps on the transmission.
- Ground G-104 or G-102 loose or corroded (figure 5). (G-104, G-102 are located at the rear of the cylinder head on 4.3L applications, and on the passenger side, at the lower corner of the bellhousing on 2.2L applications).
- A short to ground in circuit 350 (ABS control module or brake switch), which will result in a brake fuse failing. A problem in this circuit is likely to result in an ABS code and a service light. In addition, TcCC will not release and a malfunction in the operation of the cruise control will be apparent.
- Loose output or extension housing bushings on 2WD models.
- A loose or damaged toothed-wheel on the output shaft which is used for the VSS.




Figure 5

- Connector C-212 is not fully connected or it's terminals are damaged. C-212 is a 10-pin connector mounted next to the PCM (figure 6).
- The 4WD low-input circuit 1694, which feeds pin F-8 of the PCM may be intermittently shorting to ground. This will change the PCM's ratio calculation for the VSS, which may result in setting code 72.






Figure 6

Technical Bulletin #302

C/K - Full Size Pickup, Yukon, Tahoe, Suburban and Blazer

- Circuits 821 or 822 shorted to ground at the top of the bellhousing on one of the *P* style mounting clips or at one of the studs that are protruding from the cowl area (figure 4, page 12)
- Connector C-200 not fully seated or its terminals may be damaged. C-200 is located behind the right side of the instrument panel in the area of the blower motor (figure 7).
- Ground G-109 is corroded or loose. G-109 is located on the thermostat housing on gas engines (figure 8, diesel application shown.)
- Connector C-365 not fully seated or its terminals may be damaged (C-365 is connected to the vehicle speed sensor, at the sensor).
- 4WD low input circuit 1493, which feeds pin F-8 of the PCM may be intermittently shorting to ground. This changes the PCM ratio calculation for the VSS, which can result in setting a code 72 because of the perceived rpm change in the output speed calculation for the processor.



G Series - Full Size Van

- Circuits 821 or 822 are shorted to ground at the *P* style hold-down clamp on the side of the transmission (figure 9). These circuits have also been known to short to ground on the underdash bracket near the DRAC. The DRAC is located on the driver's side under the dash (figure 10, page 16).






Figure 9

Technical Bulletin #302

- Ground G-200 loose, not installed or corroded. G-200 is mounted under the driver's side of the instrument cluster next to the fuse block. It may be necessary to add an extra ground for this location. *Note: A poor ground for this circuit may also cause intermittent operation of other systems which rely on this ground for proper operation, such as the dome light and brake system circuits.*



- Grounds G-124 and G-125 are the braided ground cables between the vehicle body and the engine. If one of these straps are loose, corroded or not installed, many symptoms may result including a code 72. It is imperative that these grounds be in place and in good condition.
- Circuit 437 shorted to ground by a sheet metal screw in the vicinity of the PCM (figure 11).



Technical Bulletin #302

- Connector C-104 may be coated with undercoating, causing poor terminal contact. C-104 is a two-wire connector mounted on the driver's side of the cowl area, engine compartment side, near the bulkhead connector (figure 12).
- Connector C-100 is damaged or loose. C-100 is mounted on the driver's side of the cowl area, engine compartment side, and serves as the bulkhead connector. C-100 has been known to corrode from battery acid or fumes if the connector is not properly sealed.




Figure 12