AF 33-5 part 1



by Steve Garrett

Available in the Opel, Saturn Vue and Chevrolet Equinox, the Aisin Warner AF 33-5 is a fully automatic 5 speed transmission and is available in both a front wheel and AWD versions (Figure 1).

s part of the ever changing transmission landscape, another transmission has been introduced into the General Motors lineup. Available in the Opel, Saturn Vue and Chevrolet Equinox, the Aisin Warner AF 33-5 is a fully automatic 5 speed transmission and is available in both a front wheel and AWD versions (Figure 1). Six different ranges are available:

- Park
- Reverse
- Neutral
- Drive
- L4
- L2



TRANSMISSION SPECIFICATIONS

The AF33-5 specifications are as follows:

- Transaxle type Front wheel drive and AWD applications are available. Five-speed computer controlled with TCC.
- RPO M45 (AWD applications) RPO M09 (FWD applications).
- Manufactured in Japan.
- Towing capacity 2500 lbs.
- Transmission weight 198 lbs.

- Transmission fluid type Type T-IV (GM #88900925).
- Fluid capacity 8.2qt (7.8L).
- Pressure Taps Line pressure.
- Gear Ratios:


1st: 4.685-1

2nd: 2.942-1

3rd: 1.923-1

4th: 1.301-1 5th: 1-1

Rev: 3.177-1





Chrysler Shifter Seal Saver. (K071)

An economical way to add support to the manual control shaft at the case to help avoid seal leaks.



604 Differential Case Saver. (K039 & K049) Includes a newly developed pinion shaft to re-

oped pinion shaft to resist gear welding under extreme conditions.



Mercedes 722.6 Chico Bushing Kit. (K050)

Allows the use of the new output shaft with the earlier drum.



4L60/4L60-E 3-4 Clutch Rapid Relief Valve. (K070)

Spring loaded ball valve helps eliminate clutch drag on the release.



4T40-E Accumulator Piston. (K069)

New aluminum piston to replace the commonly broken plastic pistons.



240 & 230 Output Shaft Bearing Retainers. (K067 & K068)


Very economical, heavy duty replacement/ upgrade for OE retainers.




LOOKING FOR A SUPERIOR PRODUCT?

Call 800-451-3115 or @

www.superior-transmission.com







Hotter than Prada and Gucci.

Introducing Precision International's redesigned transmission repair kit bag. Beautiful on the outside, still the industry's best quality and dependability inside.


At Precision International, outstanding quality, performance and reliability are really our bag. But as the technological leader in transmission repair for over 30 years, we figured we should also look the part. So we've updated our transmission repair kit package. And we have to admit – our new bag is a lot easier on the eyes. Plus, as always, what's inside will make your job a lot easier as well. Look for our nifty new bag and discover how choosing proven transmission solutions from Precision International is more attractive than ever.

PRECISION INTERNATIONAL

The Problem Solvers.

210 Knickerbocker Ave., Bohemia, NY 11716
(631) 567-2000 • Fax (631) 567-2640 • Toll Free: 800-872-6649
Florida Office (954) 509-9950 • Fax (954) 509-9945
E-mail: sales@transmissionkits.com
www.transmissionkits.com

The bolt and dipstick are located on the "INBOARD" side of the transaxle.



The major mechanical components of the Aisin Warner AF33-5 are shown in figure 2 (page 12).

The major Electrical Components are shown in figure 3 (page 12).

FLUID LEVEL CHECKING PROCEDURE (figure 4):

Like several other GM transmissions, the factory fill is designed for an "extended service interval". As you know, many GM transmissions no longer use a dipstick, but instead use a sight plug. Although the AF33-5 does not have a dipstick tube, it does have a dipstick. The plastic dipstick is positioned in a location that one would not expect. It's in the case and held by a bolt that must be removed to check the fluid level. The bolt and dipstick are located on the "INBOARD" side of the transaxle.

FILLING THE TRANSMISSION WITH FLUID (figure 5):

The fluid used in the AF-33-5 is TYPE T IV synthetic (GM part # #88900925). To fill the transmission with fluid you must remove the fluid

fill plug. The fluid fill plug is located next to the P/N PRNDL switch on the top of the transmission. The fluid fill plug is a hex head style plug. It is important not to confuse the fluid fill plug with the third gear band anchor bolt. The third gear band anchor bolt is located within a few inches of the fluid fill plug. If the third gear anchor bolt is removed the band will fall out of position resulting in a "NO 3RD gear" condition even if the bolt is reinstalled. If the third gear anchor bolt has been removed you will need to remove the transmission and disassemble it to reposition the band and its anchor correctly.

The fluid is designed to give up to 50,000 miles of service if the vehicle is being operated according to the severe operating schedule or for the life of the vehicle if it is being operated according to the normal operating schedule.

CHANGING THE TRANSMISSION FILTER

Changing the filter is <u>not</u> part of the normal fluid change procedure on the AF-33-5. Like some other GM applications the filters are designed for the life of the unit. If you choose to change the filter use the following procedure:

- Remove the 8 pump bolts and remove the pump assembly
- Remove the second coast clutch hub/outer race and second coast clutch hub and washer
- Remove the 17 housing bolts and remove the housing
- Remove and replace the filter
- Reverse the procedure to install the new filter

Caution: Do not intermix the housing bolts and pump bolts or damage to the transmission will result. The housing bolts are 30mm long while the pump bolts are 28 mm long.

RESETTING THE FLUID LIFE MONITOR


The AF 33-5 GM applications are equipped with a fluid life monitor. The TCM calculates the fluid life and then signals the IPC when fluid life is less than 10%. The IPC will turn on the service vehicle soon lamp on some applications indicating that it is time for the fluid to be changed. In addition, the TCM will log a DTC 1868 indicating the transmission fluid requires service.

To fill the transmission with fluid you must remove the fluid fill plug. The fluid fill plug is located next to the P/N PRNDL switch on the top of the transmission.

The illumination of the service vehicle soon lamp, when the fluid life is low, has been disable on applications that exceed the following VIN build dates. Canada/ Mexico built vehicles after 4/07/05, USA built vehicles after 3/31/05.

The fluid life monitor system will need to be reset if any of the following are to occur:

- The ATF has been changed
- The transmission has been



replaced

The transmission has been overhauled

To reset the fluid life monitor to 100% you must use a scan tool.

Well, as you can see, our time has

run short. We'll take a more detailed look at this unit next time.



