

The background of the entire page is a composite image. The upper portion shows a car's interior, including a steering wheel, instrument cluster, and center console, viewed from a driver's perspective. The lower portion is a close-up, detailed view of an automatic transmission's internal components, such as gears and shafts, which are highly reflective and metallic. The image is framed by yellow and white geometric shapes, including a diagonal line and a corner cutout.

2013 TECHNICAL SEMINAR

Get 'em Out The Door!

ZIP KIT SHOP TALK

“We had a 2008 Range Rover diesel 157,500 km with drivability issues. We stripped the v/b and fitted all components from the Zip Kit, reinstalled v/b, new ATF and new filter, then road tested the vehicle home. Well done, boys, this Range Rover drives 100%. I didn't even reset the adaptation, it drives real good.”

*S. O'Connor
A & M Gearbox Centre
Dublin, Ireland*

“I installed our first Zip Kit on a U140F, nice kit and additional information. What was really nice: to have at your fingertips the vacuum testing locations and the effects of the wear in that bore. Without this info, I might not have vacuum tested and missed this problem. Nice kit, Sonnax.”

*K. Mumie
Foran's Transmissions
Minersville, Pa.*

Discover the newest Zip Kits at
www.sonnax.com



Scan code with your smartphone.



Become a Sonnax Insider!
Find Sonnax on Facebook or visit
www.sonnax.com to sign up for e-news.

© Sonnax Industries, Inc.

800-843-2600 • 802-463-9722 • www.sonnax.com

Sonnax is an Employee-Owned Company

sonnax® ZIP KIT®

**THE FIRST STEP
IN CORRECTING COMMON SHIFT PROBLEMS**

Simple, Drop-In Parts

Install Quickly & Easily Without Special Tools

Stops Hydraulic Leaks

So the Valve Body Works the Way It Should

In-Depth Tech Booklet

For Installation, Testing & Diagnostics;
Helps Determine if Further Repairs are Needed



**2013 TECHNICAL
SEMINAR**

Get 'em Out The Door!



The
Automatic Transmission
Rebuilders Association

2400 Latigo Avenue
Oxnard, CA 93030
Phone: (805) 604-2000
www.members.atra.com

This manual has been developed by the Automatic Transmission Rebuilders Association (ATRA) Technical Department to be used by qualified transmission technicians in conjunction with ATRA's technical seminars. Since the circumstances of its use are beyond ATRA's control, ATRA assumes no liability for the use of such information or any damages incurred through its use and application. Nothing contained in this manual is to be considered contractual or providing some form of warranty on the part of ATRA. No part of this program should be construed as recommending any procedure which is contrary to any vehicle manufacturer's recommendations. ATRA recommends only qualified transmission technicians perform the procedures in this manual.

This manual contains copyrighted material belonging to ATRA. No part of this manual may be reproduced or used in any form or by any means — graphic, electronic or mechanical, including photocopying, recording, electronic or information storage and retrieval — without express written permission from the ATRA Board of Directors.

Public exhibition or use of this material for group training or as part of a school curriculum, without express written permission from the ATRA Board of Directors is strictly prohibited.

ATRA and the ATRA logo are registered trademarks of the Automatic Transmission Rebuilders Association.

Portions of materials contained herein have been reprinted with permission of General Motors Corporation, Service Technology Group Agreement # 0610228.

Portions of materials contained herein have been reprinted with permission of Ford Motor Company.

Portions of materials contained herein have been reprinted with permission of Daimler Chrysler Corporation.

**Have you tried our NEW Honda AT Friction Modules?
Use EXEDY Honda Friction Modules for that smooth consistent shift feel.
It takes a lot to impress the OEMs, We want to impress you!**

EXEDY

EXEDY Globalparts Corporation

Friction • Damper • Fluid
WET DRY TECHNICS
EXEDY FDF

At EXEDY, we're passionate about what we do.

It's like the feeling you get when a long-time customer walks in your door with a new challenge for you: the **fact** that **13 OEMs consistently choose us** is a huge source of pride. Playing in the "big leagues" of the automotive industry requires consistent quality, continuous reliability, ingenuity and non-stop search for better efficiency. This translates into **top quality products** available to the aftermarket at **very competitive pricing**.

You're proud of what you and your skills can do for your customer,


**Ask for EXEDY in your next order and
experience what we can do for you!**

Not Just OE Quality, We ARE THE OE!

New NVR (Noise & Vibration Reduction) technology reduces gear noise giving a quiet & smooth ride

WAD (Wide Angle Damper) design enables clutch disc to hold more torque with less force

Pre-Damper mechanism reduces idling gear noise



Quality supported by OEM technology

Uses the same materials as OEM product



Excellent durability & super low wear diaphragm spring with special heat treatment (high frequency induction)

SPECIFIED ORIGINAL EQUIPMENT WORLDWIDE

For that OE Smooth Consistent Shift Quality, AT or MT!

EXEDY products are available from major parts suppliers worldwide.

Visit our website today and learn more!

www.exedyusa.com

Are you a supplier interested in carrying EXEDY products? Give us a call Today! 800.346.6091





Mission Statement

The ATRA (Automatic Transmission Rebuilders Association) is dedicated to maintaining the highest standards in the automatic transmission repair industry for work quality, customer service and business success.

ATRA Purpose Statement

The purpose of the ATRA is to maintain the highest standards in the automatic transmission repair industry for work quality, customer service and business success.

The ATRA is a source of knowledge and symbol of trust for both transmission professionals and the public. We provide the training, resources, information and advocacy to elevate the transmission repair industry; uniting the public's automotive service needs with our member's business goals, knowing that quality work, fair pricing, and visibility to the community constitutes a mutual benefit.

**New
Online
Store!**



Heated Cooler Line Flusher
Adapters Available for **All** the Latest
Transmissions!



Oberg Reusable Checkable
Filters for Flushers



Porta-Pump



E-Zee Shift, Phaze Drive,
Sensor Monitor



417.725.6400 • 800.725.6499
www.g-tec.com • sales@g-tec.com



Trany Coat



Magnet
Handles



Dyno: Transmission Road Test Simulator



Lance Wiggins
Technical Director



Welcome to ATRA's 2013 Technical Seminar!

The fact that you're here proves you're aware of just how quickly the transmission repair industry has been changing. Staying on top of those changes is far too demanding for any one technician to do alone.

That's one of the biggest benefits of the ATRA Technical Seminar program. We put the experience of thousands of technicians — from every corner of the globe — right at your fingertips. We collect their experiences, analyze them, and create educational programs that address the problems and situations that you face every day.

These are real world solutions to real world problems. And we don't just offer quick fixes: We analyze the theory and principles behind the problems, and design advanced educational programs that will help you expand beyond the problem-solution mentality... to help you become a better, more competent technician.

Through it all, we never lose sight of the most important part of your job: remaining profitable as we move forward into the most challenging era ever faced by professional automotive technicians. And make no mistake about it: It is still possible to remain profitable in today's climate of high tech diagnosis and repairs. What it takes is a commitment to service and a willingness to maintain your technical prowess. Your being here proves you have that commitment and willingness.

A handwritten signature in black ink that reads "Lance Wiggins". The signature is fluid and cursive, with a long horizontal stroke at the end.

Lance Wiggins
ATRA Technical Director



We sell reliability.

Go with a name you know and trust – Precision International.
The technological leader in transmission repair for over 30 years.

There's a lot riding on the quality and reliability of your work. That's why you can't take shortcuts when repairing a transmission. Whatever make, model or year you're working on, Precision has the best parts and kits to fix it. All are cross-checked against the latest OEM specs (with changes noted and made). All are OE quality or better. And all are guaranteed to work. Plus, our huge inventory virtually assures immediate delivery.

You can count on us

We also offer outstanding tech support, including www.transmissionkits.com – our hot new website with continually updated video seminars from leading transmission expert John Parmenter, question and answer forums, complete parts information and much more. So you can troubleshoot any problem and offer your customers the very best transmission solutions possible.



You see, at Precision, reliability isn't just an empty promise. It's the heart and soul of our business... as well as yours. For more information, give us a call.

www.transmissionkits.com


PRECISIONTM
INTERNATIONAL
The Problem Solvers.



14 Todd Court Extension, Yaphank, NY 11980
(631) 567-2000 • Fax (631) 567-2640 • Toll Free: 800-872-6649
Florida Office: 6790 Hillsdale Point, Boynton Beach, FL 33437
(561) 734-2332 • Fax (561) 734-2375
E-mail: sales@transmissionkits.com
www.transmissionkits.com



ATRA would like to thank the following companies for their continued support!



NORTHLAND TRANSMISSION, INC.
WWW.SERVOBORE.COM

Whatever It Takes

WIT
WHATEVER IT TAKES
TRANSMISSION PARTS, INC

800-940-0197

sales@wittrans.com

or buy online at
www.wittrans.com

Automatic Transmission Parts

Hard Parts

- OE Manufacturer, Aftermarket New, Remanufactured, & Used
- Clutch Drums
- Shafts
- Front Pumps
- Planets
- Valve Bodies
- Complete Line of Miscellaneous parts

Torque Converters

- Complete line of CVC Remanufactured Converters

Soft Parts

- Master Kits
- Banner Kits (Less Steels)
- Overhaul Kits
- Paper/Rubber Kits
- Filters & Kits
- Frictions
- Steels
- Bushing
- Modulators
- Washers
- Bearings
- Gaskets
- Bands
- Flex Plates & Flywheels
- Speedo Gears
- Mounts
- Coolers
- TeckPak Conversion Kits
- Superior Shift Correction Packages
- Detent Cables
- Transgo Reprogramming Kits
- Transgo Shift Kits

Standard Transmission Parts

- Rebuild Kits
- Bearing Kits with Syncro Rings
- Gasket Sets
- Gears & Shafts

Rebuilt Transmissions

- Standards
- Clutch Parts**
- Sach's & Valeo Clutch Kits (New)
 - Forks

- Pilot Bushings & Bearings
- Clutch Alignment Tools

Transfer Case Parts

- Gasket & Seals Kits
- Overhaul Kits
- Chains

Shop Supplies & Tools

- Additives
- Assembly Lubricants
- Builders Benches
- Lifts
- Parts Washer Soap
- Rough Service Light Bulbs
- R.T.V. Black, Blue, Clear
- Technical Manuals
- Tools & Equipment
- Threadlock

Remember that Old-Time Service?



Whatever It Takes Does!!!



Table of Contents

HYBRID

Hybrid Warnings.....	16
Hybrid Tools	17
Toyota Power Down.....	22
GM Power Down	26
Honda Power Down.....	28
Ford Power Down.....	29

GENERAL MOTORS

ALL GM

Transmission Identification.....	33
----------------------------------	----

4L60/65/70E

3rd and/or 4th Slips, VSS DTC's, No Forward or Slips Forward	34
Shift Feel and/or Timing Concerns, Possible DTC's	36
Ticking Noise in 3rd and/or 4th.....	37
No 2nd Gear, Shifts 1-3-4	38
TCC Shudder in Hybrid, DOD or AFM Vehicles	43

4L80E

Intermediate Clutch Failure, 1-2 Slide Bump Slips in Reverse	44
Case Failure w/ Emergency Brake Drums ...	47

6L80/90

1-2-3-4 Slip Condition, Possible No Movement Forward	48
--	----

4T65E

High Line Pressure, Harsh Shifts, After Rebuild	49
---	----

6T40

Intermittent Hard Shifts.....	50
P0723 Set.....	51

6T40/45/50

No 3rd, 5th or Reverse Gears	52
Hard Shifts, Broken 3-5-Reverse Wave Plate, Possible P0766	53
Binding on the 3-4 and 4-3 Shift, Possible P0797 Set.....	55

6T70/75

Control System Changes and Updates	
Clutch Pulse Learn	56
Redesign TEHCM	58
Redesigned Spacer Plate and Gaskets	59
Accumulator Feed, Accumulator Pistons and Springs	60
Check Ball Addition	61
Valve Body Changes	62
Low/Reverse Clutch	65
1-2-3-4 Clutch	66
3-5-Reverse Clutch	67
3-5-Reverse and 4-5-6 Clutch Housing	68
4-5-6 Clutch Housing	69
4-5-6 Clutch Piston	70
Turbine Shaft	71
End Cover.....	72

Case	73
2-6 Wave PLate	74
Torque Converter Installation.....	75

LCT 1000

Harsh Downshifts	77
Burnt 3-5-Reverse and 2-6	
Clutches Burnt	78
Stuck in Neutral, Will Not Shift, Hard Shifts	
Clunk, Reduced Engine Torque, DTC's.....	79
Fluid Venting From the Transmission	81
Pump Whine	82
MIL "ON", Shift Inhibit Mode Message "ON", Slams into Reverse	84
No Movement, PRNDL Lights Flashing, No Codes	86
TCC Cycling.....	87

MAGNA TRANSFER CASE

Updates for Models 1222, 1225, 1226, 1625, 1626, 3023, 3024	88
Programming After a Repair BW 4474	90

FORD SECTION

4F27E/FN4A-EL/FNR5

Low Line Pressure.....	94
------------------------	----

6F50/55N

No Line Rise.....	98
-------------------	----

4R70/75E

Slips or No 2nd Gear After Rebuild.....	100
TCC Cycles w/ O/D Cancelled Only	102

AODE/4R70W

TCC Code P0740 After Rebuild.....	104
TCC Apply On Top of 2nd Gear	105

1995-2001 4X4 Trucks

Misdiagnosed TCC Cycling.....	106
-------------------------------	-----

6R60

Torque Converter Cycling.....	107
-------------------------------	-----

6R80

Toque Converter Shudder 25-45 mph	108
---	-----

5R110W

Bind in Reverse, D3 and Reverse, D2 is Okay.....	109
--	-----

5R55W/S

Erratic Transmission Operation	112
Harsh Shifts/Engagements, Erratic Shifts ..	122

CFT30

Oil Pump Noise	123
Oil Pump Breakdown and Assembly Tools..	124
Valve Body.....	125
Pressure Codes P0701, P0871 and P0961 ..	126
Variator Seals	128

CVT

Universal Pulley Tool	129
-----------------------------	-----

Committed to Excellence!



Quality



Service



Satisfaction

Highest quality torque converters for domestic and foreign automotive markets, including industrial applications.



Expect the Best!



Consolidated Vehicle Converters
Visit us at cvccconverters.com

Table of Contents



CHRYSLER

ZF8HP45

Clutch and Solenoid Application Charts.....	132
Clutch Identification	133
P1 and P2 Planet Assemblies	134
P3 and P4 Planet Assemblies	135
Valve Body Breakdown	136
Oil Pump Breakdown	146

41TE/42LE/42RLE

P0740 Before and After Repair	153
Engine Stalls in Drive and/or Reverse.....	155
Engine Stalls in Drive Only, Reverse is Okay	157

41TE/42LE

Intermittent Code P1740.....	160
------------------------------	-----

42RLE

TCC Shudder After PCM Replacement.....	162
--	-----

62TE

Shudder Feeling During the Shifts	163
Loss of 3rd, 4th and/or 6th Gear After Repair.....	164
No Reverse After Repair	165
No Movement Condition.....	166

JEEP RE UNIT

No TCC Command	167
----------------------	-----

48RE

Slips or No 3rd and Reverse, High Line Pressure	168
--	-----

68RFE

Overheating Condition, Fluid May Catch Fire.....	174
Binds in 3rd, P0871 Set.....	175

IMPORT SECTION

MDRA or MDPA

Bellhousing Leak After Repair	180
-------------------------------------	-----

01M

TCC Cycling.....	184
------------------	-----

HONDA 5 SPEED 4 SHAFT MODELS

1-2 Flare, 1-2 Neutral	186
------------------------------	-----

HONDA/ACURA

Kills the Engine in Drive, No Reverse	190
---	-----

HONDA

TCC Shudder or Moan	196
TCC Shudder	197

ZF5HP18/19 RWD

Accumulator Piston Installation	198
---------------------------------------	-----

ZF6HP

Shift Complaint Caused by EMI	204
Jaguar Code P0741.....	206

AW55-50/51SN

TCC Cycling.....	207
Forward Engagement Problems.....	210

IMPORT SECTION (cont.)

RE5F22A

Harsh 2-1, 3-1 Downshift During Throttle Up After Repair	212
---	-----

722.6

Leaks Out of the Vent	213
-----------------------------	-----

722.9

Pump Failure.....	214
-------------------	-----

JF613E

Introduction	216
--------------------	-----

Component Identification and Apply Chart	217
---	-----

Solenoid and Pressure

Switch Identification	218
-----------------------------	-----

Solenoid Application Chart	221
----------------------------------	-----

Pressure Switch Function and Application Chart.....	222
--	-----

Lock Up and Reverse Clutch Hydraulic Control	223
---	-----

Main Line Pressure Control.....	224
---------------------------------	-----

Input and Output Speed Sensors	225
--------------------------------------	-----

Park Neutral Position Switch.....	226
-----------------------------------	-----

Valve Body Removal.....	227
-------------------------	-----

Case Air Checks.....	228
----------------------	-----

Pressure Testing	229
------------------------	-----

“E” Torx Shallow Head Case Bolts	231
--	-----

AWD Left Axle Stub Shaft Removal	232
--	-----

Sprag Rotation.....	233
---------------------	-----

KM TYPE UNITS

TCC Slip Codes.....	234
---------------------	-----

Automatic Transmission Parts For Vehicles From Around The World



NATPRO - National Transmission Products
Los Angeles, San Diego, Concord, Las Vegas, Phoenix, Seattle
800-333-2330

TRANSTAR
TRANSTAR INDUSTRIES, INC.®



WE ASSURE IT TO BE
TESTED
TRUSTED
TRUE

YOU TRUST US, THEY TRUST YOU.

With a True Blue Certified torque converter, your customers have a converter as good as or better than OE and backed by a 3-year/36,000 mile warranty.*



1 855 TRANSTAR | WWW.TRANSTAR1.COM

*Subject to Recon warranty terms, conditions and limitations.



RECON
TRUE BLUE
CERTIFIED

Table of Contents

FORD SECTION

4F27E/FN4A-EL/FNR5

Low Line Pressure..... 94

6F50/55N

No Line Rise..... 98

4R70/75E

Slips or No 2nd Gear After Rebuild..... 100

TCC Cycles w/ O/D Cancelled Only..... 102

AODE/4R70W

TCC Code P0740 After Rebuild..... 104

TCC Apply On Top of 2nd Gear 105

1995-2001 4X4 Trucks

Misdiagnosed TCC Cycling..... 106

6R60

Torque Converter Cycling..... 107

6R80

Toque Converter Shudder 25-45 mph 108

5R110W

Bind in Reverse, D3 and Reverse,
D2 is Okay..... 109

5R55W/S

Erratic Transmission Operation 112

Harsh Shifts/Engagements, Erratic Shifts . 122

CFT30

Oil Pump Noise 123

Oil Pump Breakdown and Assembly Tools.. 124

Valve Body..... 125

Pressure Codes P0701, P0871 and P0961 .. 126

Variator Seals 128

CVT

Universal Pulley Tool 129

4F27E/FN4A-EL/FNR5

Low Line Pressure

Late and soft 1-2 shifts, no movement in manual 1 and/or erratic shifts can all be caused by low line pressure. The majority of the time these symptoms may be caused by the solenoid regulator or pressure regulator valve wear.

However these symptoms can also be caused by a defective PWM solenoid “E” and/or the EPC solenoid. Knowing which direction to diagnose this concern will greatly improve your repair time.

To address these concerns clear any codes first, attach a gauge, and check the line pressure at a hot idle in Neutral and Drive. The minimum line pressure should be between 48-62 psi.

The transmission must not be in fail safe mode while checking minimum line pressure. Maximum line pressure in drive should be between 180-205 psi at a brief wide open stall. You can also check maximum line pressure with the solenoid connector disconnected in drive at 1200 RPM (do not check at idle).

No Movement in Manual 1

If pressure is low in manual 1, the clutch control valve can't be shifted into the correct position because the solenoid regulator oil pressure is low.

With the clutch control valve in the wrong position, solenoid “B” oil will be misrouted to the TCC control valve. When the TCC control valve moves it will shut off the forward clutch apply pressure.

Line Pressure Tap



4F27E/FN4A-EL/FNR5


Low Line Pressure (continued)

If solenoid “E” is not fully seated (leaking) when commanded “ON/Closed”, it will retain pressure on the release side of the 2-4 servo piston. This pressure will oppose the band apply pressure during the 1-2 shift causing a slow band apply. When selecting manual 1, if solenoid “E” produces more than 8 PSI, the pressure will stroke the solenoid shift valve. When the solenoid shift valve is upshifted, this will redirect solenoid “A” pressure to the 3-4 shift valve and shut off the forward clutch apply pressure.

If the line pressure is within specification, replace Solenoid “E” and retest. If the complaint(s) still persists, remove the valve body and inspect the pressure regulator and solenoid regulator bore for wear. Correct any wear problems in these areas. **Note: Refer to Ford solenoid ID for Solenoid “E”**

Solenoid Identification

Mazda ID	“SSA”	“SSC”	“SSB”	PWM Solenoids
Ford ID	“SSC”	“SSE”	“SSD”	PWM Solenoids




Ford ID	EPC	SSA	SSB
Mazda ID	EPC	SSD	SSE

4F27E/FN4A-EL/FNR5

Low Line Pressure (continued)

Remove the valves shown. Carefully inspect and test the valve bores. When you look closely, you can see the ridge that is formed from excessive bore wear. If the transmission is on the bench it's advisable to sleeve the servo pin bore. Be sure to check the FNR5 for similar wear problems.



4F27E/FN4A-EL/FNR5

Low Line Pressure (continued)

The valve body contains six solenoid valves:

- three PWM solenoid valves (pulse width modulation solenoid valves)
- two shift solenoid (on/off) valves
- one main regulating valve (variable force solenoid)

The individual clutches and bands are supplied pressure from the PWM solenoid valves and the shift solenoid (on/off) valves and thus the gears are shifted. The PWM solenoid valves allow direct actuation of the clutches and bands to ensure extremely smooth gear shifting through precise pressure regulation.

The shift solenoid (on/off) valves switch the hydraulic path to the clutches and bands, reducing the number of required modulating valves. The main regulating valve and EPC solenoid ensures that sufficient hydraulic pressure is available in all operating conditions.

4F27E Solenoid Firing Order


Ford	EPC	Sol A	Sol B	PWM C	PWM D	PWM E
Mazda	EPC	Sol D	Sol E	PWM A	PWM B	PWM C
Sol Status	N-APP	N-APP	N-APP	N-Vent	N-Vent	N-Vent
Park-Neut	Reg	On	Off	Off	Off	Off
Reverse	Reg	Off	Off	Off	Off	Off
D 1st	Reg	Off	Off	Off	On	On
D 2nd	Reg	Off	Off	Off	Off	On
D 2nd TCC	Reg	Off	On	On	Off	On
D 3rd	Reg	Off	Off	Off	Off	Off
D 3rd TCC	Reg	Off	On	On	Off	Off
D 4th	Reg	On	Off	On	Off	Off
D 4th TCC	Reg	On	On	On	Off	Off
Man 2nd	Reg	On	On	Off	Off	On
Man 1st	Reg	Off	Off	Off	Off	On

6F50N

No Line Rise

During the rebuild process it is very important to inspect the isolator valve and spring. If the valve spring breaks the end plug can move inboard and exhaust EPC pressure. This will result in no line pressure rise. The working height is 0.980" at a weight of 14 lbs.


1.473" X .337" X .043"
Plain




6F50N

No Line Rise (continued)

The isolator valve is really an accumulator for the line pressure control (LPC) circuit. The isolator valve smooths out the pulses from the LPC solenoid.



When the isolator valve spring breaks the end plug has room to move towards the middle of the valve body. This allows LPC oil to exhaust back into the sump and cause low line pressure.




4R70/75E

Slips or No 2nd Gear After Rebuild

A slip into 2nd gear at medium to heavy throttle or no 2nd gear apply at all after rebuild may be caused by intermediate air bleed capsule misalignment.

The air bleed capsule in the intermediate piston must be properly aligned in relation to the spring retainer. If the bleed capsule is not at the 12 o'clock position it may come in contact with the spring retainer. This will push the capsule out of the piston and cause 2nd gear problems.



On earlier models the spring retainer and piston aligned into the pump. Instead of a air bleed capsule there is only a small orifice in the piston. This orifice could be positioned anywhere without hitting anything.

The only problem on these models, if the air bleed was placed at the 6 o'clock position it would trap air in the circuit. This mistake may cause a long 1-2 shift, during the first shift of the morning or after sitting several hours.

4R70/75E

Slips or No 2nd Gear After Rebuild (continued)

Air Bleed Check Ball Capsule Pushed Out Of Piston



Air Bleed Check Ball Capsule Falls Out Out When Piston Is Removed





4R70/75E


TCC Cycles With O/D Cancelled Only

A no lockup or cycling in and out of lockup when the overdrive is cancelled may be caused by the intake air temperature sensor signal. With the transmission in overdrive mode (not cancelled) the lockup would work fine. There may or may not be any codes associated with this concern. Replacement of the air intake sensor will likely fix the problem.

Typical Integrated Intake Air Temperature (IAT) Sensor Incorporated Into A Drop-In Or Flange-Type MAF Sensor




PIN	Function
1	IAT Signal
2	IAT Return
3	MAF Signal
4	MAF Return
5	Ground
6	Voltage Supply



EVT PARTS

WHEN GETTING IT NOW...
IS A MUST!



Hard Parts * Soft Parts * Converters



We offer a wide variety of hard parts, soft parts, and converters to the automotive industry, attested by over 50 years quality customer relations and service in the distribution of automatic transmission parts.



www.evtparts.com

1155 N. McKinley Ave., Los Angeles, CA 90059 Tel: 323-758-1302 Fax: 323-758-9999
Toll-Free: 866-EVT-PARTS (388-7278) SE HABLA ESPANOL

AODE/4R70W

TCC Code P0740 After Rebuild

After rebuilding a 4R70W transmission a P0741 (TCC slip code) sets during the road test. This could be caused by replacing a damaged 4R70W planet assembly with a planet assembly from an AODE during the rebuild. There is a difference in ratio between the AODE and 4R70W planet assemblies. The information shown below will identify the different tooth counts for each component.

Reverse Sun Gear / Sun Gear Shell



AODE	4R70W
36 Teeth	38 Teeth

Forward Clutch Sun Gear



AODE	4R70W
30 Teeth	31 Teeth

Planetary Carrier Assembly (Both Long & Short Pinions)



AODE	4R70W
18 Teeth	25 Teeth

Output Shaft Ring Gear




AODE	4R70W
72 Teeth	88 Teeth

AODE/4R70W

TCC Apply On Top of 2nd Gear

Ford vehicles equipped with an AODE or 4R70W transmission with a complaint of lockup apply on top of 2nd gear. This problem may be caused by a Cylinder Head Temperature (CHT) sensor malfunction on some models. Check the CHT sensor for a proper reading.

There may be no codes present for the cylinder head temp sensor stored in memory. Use the chart to verify if the cylinder head temp sensor is working correctly. Use a temperature probe to verify cylinder head temperature.



(1) Value may vary by 15%.

(2) At this temperature, there is a voltage overlap zone where it is possible to have either a cold end (low voltage) or hot end (high voltage) reading at the same temperature. Either voltage specification listed is correct.

Temperature F (C)	(1) Volts	(1) Ohms
32 (0)	4.14	96,255
68 (20)	3.26	37,387
104 (40)	2.23	16,043
158 (70)	1.04	5268
185 (85) (2)	.69 or 3.68	3215
194 (90) (2)	.60 or 3.71	2750
212 (100) (2)	.46 or 3.41	2034
248 (120)	2.74	1155
284 (140)	2.10	689
302 (150)	1.80	542
320 (160)	1.55	430

1995 To 2001 Ford 4X4 Trucks

Misdiagnosed TCC Cycling

A complaint of engine surging between 35 to 45 mph, may be mistaken as a TCC cycling concern. This symptom may be caused by the vehicle having different size tires. All 4 tires must be the same brand, and have the same amount of air pressure and tire wear. This complaint may appear on a high mileage vehicle after a flat tire was replaced with a new spare that has no wear at all.

The wrong size tires will cause binding and the transfer case control module will constantly adjust the torque from the front and rear wheels. Giving the vehicle a surging sensation while driving on dry pavement.

Ford trucks equipped with a Borg Warner 44-05 transfer case with Torque On Demand (TOD) referred to as Control Trac. This is a constant all wheel drive system, there are no selection buttons or knobs on the dash for the driver to control 4 wheel drive.

Borg Warner 44-05



6R60

Torque Converter Cycling

A complaint of a torque converter cycling or hanging in a lower gear after a forced kick down shift during cruise control operation at higher temperatures maybe caused by a calibration issue. There may also be an intermittent cold hesitation, surge, engine cooling fan noise and/or varying A/C discharge temperatures “only” during low speeds all caused by a calibration issues.

The vehicles affected are the 2006-2007 Ford Explorer 4 door/Mercury Mountaineer and 2007 Sport Trac vehicles equipped with a 4.0L engine and a 6R60 transmission.

There’s a new calibration released December, 2012 B43.16 or B44.8 and higher. This calibration can be obtained at www.motorcraft.com.



6R60

6R80

Torque Converter Shudder Between 25-45 mph

Some 2010 Ford F150 equipped with a 4.6L engine and a 6R80 transmission built on or before 12/1/2009. May have a complaint of a torque converter shudder during low speed during light throttle acceleration between 25 to 45 mph (40-72 km/h).

The shudder and/or vibration may also be felt during downshifts and is followed by a light throttle tip in. Ford has released a new calibration to correct this concern. Refer to TSB # 10-25-13 for details.

2010 Ford F-150
Receives
Minor Updates




6R80

5R110W

Bind In Reverse, D3 and Low, D2 Is Okay

The transmission may exhibit an unusual bind in Reverse, Drive 3, and Manual Low; Drive 2 is working fine. The transmission may feel like it's taking off in a higher gear than 1st in the O/D position.

In 2006-and-later model 5R110W, the O/D pressure plate has a raised, stepped area on one side with an extended tab toward one lug. These plates are found mostly in the 5R110W with the PTO setup. These plates are "NOT" interchangeable!



After taking a close look at the transmission clutch apply chart, the one common denominator for a bind in all these ranges would be if the overdrive clutches were staying on all the time. The coast clutch is on in Reverse, Manual 3 and Manual 1, causing the bind. But it's not on in Manual 2 or the Drive range so it'll move, even though feels like it's in a higher gear.

Component Apply Chart								
Range	Engine Braking	Forward Clutch	Coast Clutch	Overdrive Clutch	Int. Clutch	Direct Clutch	Low/Reverse	Ratio
P							A (a) (b)	
R			A			A (c)	A (a)	2.88:1
N							A (a) (b)	
O/D 1		A (c)					A (a) (b)	3.09:1
O/D 2		A (c)		A				2.2:1
O/D 3		A (c)			A			1.538:1
O/D 4 COLD		A (c)		A	A			1.096:1
O/D 5		A (c)				A		1:1
O/D 6		A (c)		A		A		.0712:1
MAN 3	Yes	A (c)	A		A			1.538:1
MAN 2	Yes	A (c)		A				2.2:1
MAN 1	Yes	A (c)	A					3.09:1

Cold -15°C (5°F)
 (a) Commanded pressures viewed on scanner
 (b) 30 psi until 3 mph
 (c) Clutch applied through the manual valve

5R110W


Bind In Reverse, D3 and Low, D2 Is Okay

(continued)

When you install the plate in the case, the extended tab is supposed to face the valve body, or the 6 o'clock position with the flat side up. If you don't place the snap ring opening in the proper location during a rebuild (incorrect installation shown below), the O/D clutches will mechanically lock when you bolt the pump to the case. If you make this mistake, you'll have no choice but to remove the transmission from the vehicle and correct it.



**Incorrect Snap Ring Location
This Area Must Be Kept Open**



You can see the clutches through a small opening in the main case. You can check the clutches for free play through this opening with a scribe or thin screwdriver. You should feel noticeable movement in the clutches and steels to verify that they aren't clamped down.



SUPERIOR Innovation!

Builders Are "Making The Shift To..."™ SUPERIOR

Now you Do have a Choice to be... **SUPER COOL!**

The New 5R55W/N/S Shift Correction Package developed in conjunction with TransLab Engineered & Superior Transmission Parts, Inc. is finally the Simple Solution to this problematic unit!

Due to the factory design of no cooler flow cold, it is extremely temperamental to fill and get a correct level, as well as running extremely hot compared to others without flow control systems. We finally broke thru with our patent pending Sure-Cool™ Full Time Cooler Flow Valve along with enhanced Lube system that nearly Triples the Flow thru the cooler and parts, especially the O.D. Planetary. These Flow Control Upgrades virtually eliminate front Planetary Burn-up due to lack of Poor / No lube. This new system also furnishes a built in cooler bypass system that if the unit is extremely cold (fluid starts to gel) or in the event the cooler is blocked/restricted, flow to the parts still occurs – protecting your investment.



Loose OD Bands?



PROBLEM SOLVED!

Introducing Superior's New AOD-E/4R70W/4R75W Adjust-A-Pin™

Toyota & Lexus



Superior's New U140-U250 TransLab Engineered Valve Body Upgrade Kit

SUPERIOR

TRANSMISSION PARTS, INC.™

THE SIMPLE SOLUTION™

FOR MORE INFORMATION OR
HELP LOCATING A DISTRIBUTOR
NEAR YOU CALL US TOLL FREE AT

800-451-3115

OR VISIT OUR WEBSITE AT
www.superiortransmission.com

5R55W/S

Erratic Transmission Operation

After rebuilding a 5R55W/S model transmission, during the road test you may encounter a flare on the 2-3 shift.

This concern can be caused by a new solenoid pack. Over the years, Ford has made a few changes to these solenoids; changes that can make a slight difference in the pressure they deliver to various systems in the transmission. And it doesn't take much of a pressure variation to alter transmission performance in a big way.


Here's how the application goes: 2002-03 Ford with 5R55W or S, and 2003 Lincoln with 5R55S, these are the early models, and they require the early design solenoid pack, Ford P/N 1L2Z-7G391-AG. 2004-on Ford with 5R55W or S, and 2004-06 Lincoln with 5R55S, these are the later models, and they require the later design solenoid pack:

- Original design #4L2Z-7G391-AA
- Updated design # 9L2Z-7G391-A

Ford recommends using only the updated design for these later transmissions. So it's one solenoid pack for the early units, and a newer, updated solenoid pack for the later ones. Replace the solenoid pack with the correct one for the vehicle you're working on. Use the part numbers to identify which one you have and which one you should be using.

Solenoid Operation: To get a handle on the problem with using the wrong solenoid pack, you need to understand how the system uses these solenoids to control the transmission operation. The pressure regulator setup in the valve body is typical.

Ford design: It has three boost passages in the boost sleeve. In the earlier units the three passages were TV, cutback, and reverse boost. In the later units the passages are TV1 (controlled by PCA), TV2 (controlled by PCB), and reverse boost (controlled by the manual valve).



5R55W/S


Erratic Transmission Operation (continued)

In the boost setup, there are two boost valves: one rests against the regulator valve springs, the other is notched on both sides and is used by TV1 and TV2. When PCA applies pressure to the back of the notched boost valve, it works like all other boost valves: It pushes the pressure regulator valve to the high pressure side of the circuit.

The pressure control solenoids PCA, PCB, and PCC are variable force solenoids operated by PCM commands. PCA and PCB are the primary solenoids used to raise and lower mainline pressure, based on variations in throttle position. They control pressure boost in all gear ranges from Park to Manual 1.

PCC controls reverse engagement pressure, and is directly responsible for direct clutch application in overdrive 4th, 5th, and manual 4th gears. All of the other solenoids are on-off type shift solenoids.

The PCM uses PCA and PCB to adjust mainline pressure and move or modulate other valves. During normal operation the solenoids are pulse width modulated; these modulations have three basic ranges: lower pressure, variable pressure, and higher pressure.



5R55W/S


Erratic Transmission Operation (continued)

Both solenoids can be on at the same time, but the PCM supplies opposite commands to them: Simply put, when PCA is at higher pressure, PCB is at lower pressure; when PCB is at higher pressure, PCA goes lower pressure. This causes the boost valves to split apart from one another.

The solenoids have a direct effect on shift timing and feel. The majority of the problems are either soft, flare shifts or harsh downshifts. Typically the flare shifts are on the 2-3 shift.

Other Checks: while a startling number of these calls involve solenoid application problems, there are a few other things you should look at if faced with these complaints:


- Take a close look at the pressure regulator valve setup. Look for wear marks and replace the valve, sleeve, or the entire setup, depending on the wear you discover.
- Examine the overdrive and intermediate servo control valves and plugs. Worn plugs can leak, especially during engagements and shift timing sequences.



5R55W/S

Erratic Transmission Operation (continued)


These solenoids are used for more than just controlling pressure. PCA is also used for the VFS1 modulator valve. VFS1 pressure applies the intermediate servo in 3rd gear, and applies the low/reverse servo in manual 1 and 2.



5R55W/S

Erratic Transmission Operation (continued)


PCB also controls the VFS2 modulator valve, and forward and reverse engagement valves. The VFS2 pressure indirectly affects the feel of forward engagement and the direct clutch engagement in reverse, and it directly applies the overdrive servo and the coast clutch.



5R55W/S

Erratic Transmission Operation (continued)

PCC regulates the reverse pressure modulator and reverse engagement control valves. The solenoid indirectly affects the feel of the direct clutch engagement in reverse, and directly applies the direct clutch in 4th and 5th gears.




5R55W/S

Erratic Transmission Operation (continued)

The forward clutch is applied in all forward gears. From 1st to 2nd gear the forward clutch and the overdrive servo are applied. This is just like the 5R55E-series transmissions; the forward clutch and overdrive band are applied for 2nd gear. From 2nd to 3rd gear, the overdrive band releases at the same time the intermediate band applies.


This release-and-apply process has to be precise to create a smooth, acceptable shift into 3rd gear. A slight timing variation and you can expect a flare or harsh shift.



5R55W/S

Erratic Transmission Operation (continued)

Clutch apply timing has to be very precise for this transmission to shift properly and those clutches are being controlled by the solenoids. But what if one solenoid creates an entirely different pressure than another solenoid from the same computer signal? Turns out that's exactly what happens if you use the wrong solenoid pack.





5R55W/S

Erratic Transmission Operation (continued)

After many tests and countless hours reading hydraulic schematics, measuring valves, and applying the math. We discovered; there's a slight difference, but a difference nonetheless in solenoid output. When we tested the PCA solenoids from the different solenoid packs, we found that at 0.6 amps, there was a 4 psi difference.

That doesn't sound like much but it becomes a big deal when it comes to overall pressure in the system. The 4 psi difference equates to about 30 psi of mainline pressure, enough to cause the problems we've been encountering. In nearly every case, replacing the solenoid pack corrects the problem.



Here's your Haul Pass.



**NOW
AVAILABLE**

ALLISON (2000-2012) 1000/2000	5R110W (2005-2011)
C1 Internal Spline.....GPZ185	Forward.....GPZ155
C1 External Spline.....GPZ190	Intermediate.....GPZ160
C2.....GPZ175	Direct.....GPZ165
C1 GPZ TorqKit...RGPZ-1001	Overdrive.....GPZ170
C2 GPZ TorqKit...RGPZ-1002	
C3/C4 GPZ TorqKit...RGPZ-1003	A518, A618, (1988-2007) 46/47/48RE
C5.....R566030	Overdrive Brake...GPZ115
Complete GPZ TorqKit Module...RGPZ-1000	

Raybestos
POWERTRAIN



For other key GPZ applications go to www.RaybestosPowertrain.com/GPZ or call 1-800-729-7763.

5R55S

Harsh Shifts, Engagements and/or Erratic Shuttle Shifts

Complaints of a harsh shifts, engagements and/or erratic shuttle shifts found on 2003-04 Lincoln LS and Aviators only. There may or may not be codes set, such as P1744.

The ECM's have been reflashed on several of these vehicles but it doesn't fix the problem. The module connections were inspected closely for corrosion and no problems were found. The valve bodies were also changed without any luck.

When line pressure was checked on the driver's side tap it was extremely high. In some cases the module was tapped with a large screw driver and pressure dropped and shifts were normal. At times the pressure may only drop and rise back up. In these cases only a new module corrected the problem.



CFT 30

Oil Pump Noise

The CFT 30 has a unique oil pump that uses eight pistons with springs, that are located radially around the circumference of the pump eccentric. The pistons are driven by the torque converter.

A noise concern that may be accompanied with low pressure and codes that sounds like a flexplate failure may be caused by the pump assembly. As with any noise, you need to verify the conditions.

Does the noise change with wheel speed? Does the noise happen all the time? Does the noise get louder or softer in different ranges? Obviously, if it's hard to tell or undetermined you have to start removing components.

In this case it sure sounded like a broken flexplate or flywheel. We removed the transmission and inspected the flexplate: There was no damage. So what could be causing the noise?

The CFT 30 has springs in the pump rotor area, so we decided to remove the pump and inspect them. We found a broken spring in the pump rotor. You have two options for repairing this: replace the pump assembly or replace the spring. The spring dimension free length is 1.715", the diameter is 0.553" and the coil diameter is 0.083". The working height is 1.312" at a weight of 40lbs.



CFT 30


Oil Pump Breakdown and Assembly Tools

This pump is different than anything we have seen in an automatic transmission. The technical name for this pump is “Outside impinged radial pump”. This design pump is very efficient and capable of producing several thousand pounds of pressure. Most CVT transmissions run anywhere from 250 to 1000 psi so this type of pump is a perfect fit for the CFT 30.

The pump can be taken apart to be cleaned and reassembled fairly easily with a hand built special tool. Use eight modified 3 inch C clamps to compress the pistons to install the ring and the eccentric.



Remove the eccentric then pry out the contact ring.



Chopped C Clamp


Compress the pistons and springs to install the contact ring.

CFT 30 Valve Body

The valve body has five solenoids: a main pressure control solenoid (PCA-A), torque converter clutch solenoid (TCC), primary pulley pressure solenoid (PCB), secondary pulley pressure solenoid (PCC), and forward and reverse clutch apply solenoid (PCD). All solenoids measure at 5.4 Ohms.

1. PCA Mainline Pressure Solenoid
2. PCB Primary Variator Pressure
3. PCC Secondary Variator Pressure
4. PCD Forward and Reverse Clutch Pressure
5. TCC Application Pressure TCC

Varies according to Load
Varies with Ratio Command
Varies with Ratio Command
<10 mA @ idle in D or Rev
Varies according to Load



CFT 30

Pressure Codes P0701, P0871 and P0961

This transmission has about 54 trouble codes associated with it, all of which end up with replacing the transmission, valve body, or Mechatronic unit.

Code P0701 indicates the TCM has a problem; simply put, there's something wrong with the transmission but the computer doesn't know what it is.

Code P0871 is a secondary fluid pressure sensor failure, and P0961 (PCA) pressure control solenoid A is out of range.

Code P0961 will set if mainline pressure is lower or higher than expected. This indicates a defective pressure sensor or a leak in the hydraulic system.

Code P0871 DTC will be set if the secondary variator (pulley) pressure is lower or higher than expected. This indicates a defective pressure sensor or a leak in the hydraulic system. During the initial diagnostics you need to check the pressures. Unfortunately this transmission doesn't have any external pressure ports.

To check the pressure readings on this unit use a scan tool. There are PIDS for pressure readings in the data stream. In fact, there are 45 PIDS to choose from: in this example we're going to monitor PCA-A, PCA-MES, PCC-C, and PCC-MES.

Normal pressures should be somewhere close to between 220-250 psi. If the PCC-MES PID pressures drop below the specified pressure, you have a leak in the system. Shortly after this happens the vehicle will go into limp mode.

Sometimes when the transmission is cold the unit will work pretty well, but as it gets hot it starts having issues. This isn't a Mechatronic unit problem because there is no command for low pressure. This is a valve body or sealing issue.

After disassembling the unit we found the forward clutch drum O-rings were cut and damaged. There are aftermarket companies offering seal kits and replacement parts for this unit. Replacing the seals fixed this unit, and resealing the transmission was simple with no hassles.

CFT 30

*Pressure Codes P0701, P0871 and P0961
(continued)*

Always inspect the
forward clutch sealing
rings for damage.



CFT 30


Variator Seals

There are other pressure issues that are associated with pressure codes. One common problem we're starting to see is variator tube failure.

We have two covers on the end of the unit: one is the primary variator cover; the other is the secondary variator cover. These feed tubes supply pressure to the variators.

You can replace the feed tube seals and sealing rings without taking the variators and belt out of the case.


Always replace the tube seals



CVT Pulley Tool

Universal Tool


Some shops are making a universal CVT pulley tool. The diagram below is a general idea of how the tool should look. With some angle iron, threaded rods with bolts a general pulley tool can be made.



The SF-99 SERVO PIN BORE REPAIR SYSTEM

From
NORTHLAND TRANSMISSION, INC.

"Saving the case since 1999"



The SF-99 servo pin bore repair system is a set of tools that allow you to easily repair worn servo pin bores with no special machinery, all that is needed is a drill and a hammer.

The system is available for:

- CD4E
- 5R55W/S/N
- C3/A4LD/4/5R44/55E
- AOD/E/4R70/5W/E
- AX4S/N/4F50N
- 180/4L30E
- 700/4L60E
- 375/400/4L80E
- 4T60/65E
- 4T80E
- 4F27E/FNR5
- 4EAT-F/F4A-EL
- 4EAT-G/G4A-EL
- AF20/21
- AW55-50SN

We also offer these stand alone tools & parts:

TFTV: Throttle valve repair for Torque Flights from TF-6's through 48RE.

TF-Detent: Rooster comb detent bore for Torque Flight valve bodies from TF-6's through 48RE.

RFE Gauge: Line pressure test adaptor for RFE style transmissions. Our tool offers multiple ports and lines, allowing you to safely position the adaptor.

Reverse Servo Pin: Correctly dimensioned steel reverse servo pin for 46RE/H

48RE Plate: Steel plate for sealing the flange gap between 48RE's and the transfer case.



5RW: 5R55W/S/N. The 5RW kit repairs both the intermediate and overdrive servo pin bores, stopping the leak of both apply and release oil from both servos.

4F27: 4F27E & FNR-5 (FN4A-EL, FS5A-EL). The 4F27 sub-kit repairs the 2/4 servo pin bore, stopping the leak of direct clutch oil.



Northland Transmission Inc.

105 E. Poplar Ave
Cameron, WI 54822

Phone: (715) 458-2617
Fax: (715) 458-2611

www.servobore.com

U.S. Patent # 6,192,567



ROTUNDA

Our 5RW & 4F27 servo bore kits are Ford Motor Company approved tools.