



Transmission: 4R44E/4R55E
Subject: Low line pressure in all ranges
Application: Ford
Issue Date: August, 1997

4R44E/4R55E

Low Line Pressure in All Ranges

A low line pressure condition on a 4R44E or 4R55E can occur if the rear lube orifice puck is modified or removed. This puck is the same as those used in the A4LD for servo release orificing for second and fourth gears.

