



# Technical Bulletin # 1334

Transmission: 4L60E/65E, 4L70E

Subject: Updated Bellhousing Bolts

Application: 2010 GM Vehicles

Issue Date: July, 2010

## 4L60E/65E, 4L70E Updated Bellhousing Bolts

While working on a 2010 G.M. vehicle with a 4L60E, 4L65E & 4L70E transmission, you may find that the bellhousing bolts have been changed to a new design "Plus Torq" Bit bolt (bolt #1) or a "Mor Torq" Bit bolt (bolt #2). The new design bolts require a special tool. For the "Plus Torq" bolt, tool # J41510 T-50 Plus B, and for the "Mor Torq" Bit, the part number is DT-49037 MorTorq Bit.

